PATENT

PD = 00.015333

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

& TRADENT		
In re Patent of:)	
	:	Examiner: A. Sefer
CHIORI MOCHIZUKI ET AL.)	Group Art Unit: 2826
Appl. No.: 09/845,284	·)	Group Art Omt. 2020
••	:	
Filed: May 1, 2001)	
For: SEMICONDUCTOR DEVICE	;	/
U.S. Patent No.: US 6,812,494 B2	;	
Issued: November 2, 2004	;	January 13, 2005
Commissioner for Patents		
P.O. Box 1450		Certificate
Alexandria, VA 22313-1450		
		JAN 2 5 2005

CERTIFICATE OF CORRECTION

<u>UNDER RULES 322 AND 323</u>

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

01/19/2005 AWONDAF2 00000011 6812494

01 FC:1811

100.00 OP

of Correction

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

John A. Krause

Attorney for Patentees Registration No. 24,613

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY_MAIN 475724v1

Staple Here Only! ARINTER'S TRIM

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,812,494 B2

DATED

NOVEMBER 2, 2004

INVENTOR(S) :

CHIORI MOCHIZUKI ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 20, "paid" should read --made--;

Line 35, "denotes" should read --denote--; and

Line 42, "denotes" should read --denote--.

COLUMN 3

Line 58, "convesion" should read --conversion--.

COLUMN 4

Line 64, "is" should read -- are--.

COLUMN 5

Line 61, "mouting" should read --mounting--.

COLUMN 6

Line 4, "bondig" should read --bonding--;

Line 8, "TFTS." should read --TFTs.--;

Line 13, "denotes" should read --denote--;

Line 16, "file 43" should read --film 43--;

Line 21, "liens" should read --lines--;

Line 32, "means" should read --means of--;

Line 54, "on are" should read --on one--; and

Line 61, "denotes" should read --denote--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

NY_MAIN 475724v1

PATENT NO. <u>US 6,812,494 B2</u>

No. of add'l. copies @ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,812,494 B2

DATED

NOVEMBER 2, 2004

INVENTOR(S) :

CHIORI MOCHIZUKI ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7

Line 54, "TFTS." should read --TFTs.--; and Line 62, "conparison" should read --comparison--.

COLUMN 8

Line 4, "statify" should read --satisfy--; Line 14, "an" should be deleted; Line 28, "denotes" should read --denote--; and Line 30, "denotes" should read --denote--.

COLUMN 9

Line 43, "(e.g." should read --(e.g.,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>US 6,812,494 B2</u>

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82)

NY_MAIN 475724v1

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,812,494 B2

DATED

NOVEMBER 2, 2004

INVENTOR(S) :

CHIORI MOCHIZUKI ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 20, "paid" should read --made--;

Line 35, "denotes" should read --denote--; and

Line 42, "denotes" should read --denote--.

COLUMN 3

Line 58, "convesion" should read --conversion--.

COLUMN 4

Line 64, "is" should read --are--.

COLUMN 5

Line 61, "mouting" should read --mounting--.

COLUMN 6

Line 4, "bondig" should read --bonding--;

Line 8, "TFTS." should read --TFTs.--;

Line 13, "denotes" should read --denote--:

Line 16, "file 43" should read --film 43--;

Line 21, "liens" should read --lines--;

Line 32, "means" should read --means of--;

Line 54, "on are" should read --on one--; and

Line 61, "denotes" should read --denote--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

PATENT NO. <u>US 6,812,494 B2</u>

No. of add'i. copies @ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,812,494 B2

DATED

NOVEMBER 2, 2004

INVENTOR(S) :

CHIORI MOCHIZUKI ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7

Line 54, "TFTS." should read --TFTs.--; and Line 62, "conparison" should read --comparison--.

COLUMN 8

Line 4, "statify" should read --satisfy--; Line 14, "an" should be deleted; Line 28, "denotes" should read --denote--; and Line 30, "denotes" should read --denote--.

COLUMN 9

Line 43, "(e.g." should read --(e.g.,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

NY_MAIN 475724v1

PATENT NO. <u>US 6,812,494 B2</u>

No. of add'l. copies @ 30¢ per page

